

SecurityScan Inspection Certificate

For

2018 Sample Inspection Report
123 Main Street
Building Phone - (615) 337-9710
Anywhere, State 90009

Tested to applicable Standards

This Inspection was performed in accordance with applicable Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.

*Monthly Inspection
Inspection Date
Jan 2, 2018*

Building: 2018 Sample Inspection Report
Contact: John Williams
Title: Property Manager

Company: BuildingReports Demonstration Company
Contact: Nathan A. Simon
Title: Midwest Accounts Manager

Executive Summary

Generated by: *BuildingReports.com*

Building Information		
Building: 2018 Sample Inspection Report	Contact: John Williams	
Address: 123 Main Street	Phone: 555-555-5556	
Address: Building Phone - (615) 337-9710	Fax:	
City/State/Zip: Anywhere, State 90009	Mobile:	
Country: United States of America	Email:	
Inspection Performed By		
Company: BuildingReports Demonstration Company	Inspector: Nathan A. Simon	
Address: 1325 Satellite Blvd	Phone: 7704951993	
Address: Suite 1607	Fax:	
City/State/Zip: Suwanee, Georgia	Mobile: 4146883488	
Country: United States	Email: nsimon@buildingreports.com	
Monitoring		
Type: Digital Communicator	Mfg: Radionics	Model #: 5406
Test Time/Date: 1/2/18 8:39:32 AM	Restore Time:	

Inspection Summary

Category:	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Personnel	9	16.67%	9	100.00%	7	77.78%	2	22.22%
Perimeter	10	18.52%	7	70.00%	5	71.43%	2	28.57%
Nurse Call	6	11.11%	6	100.00%	6	100.00%	0	0%
Access	13	24.07%	13	100.00%	12	92.31%	1	7.69%
Video	3	5.56%	3	100.00%	2	66.67%	1	33.33%
Control	7	12.96%	7	100.00%	7	100.00%	0	0%
Alarm	6	11.11%	6	100.00%	6	100.00%	0	0%
Totals	54	100%	51	94.44%	45	88.24%	6	11.76%

Certification

Company: BuildingReports Demonstration Company

Inspector: Nathan A. Simon



Signed: Feb 28, 2017

Building: 2018 Sample Inspection Report

Contact: John Williams



Signed: Feb 28, 2017

Discrepancy Report

Generated by: BuildingReports.com

Building: 2018 Sample Inspection Report				
<p><i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i></p>				
Device Type	Manufacturer	ModelNumber	Date	Qty
Items listed for Recall by Manufacturer				
Power Supply	Cooper Wheelock	PS-12/24-8MP	06/13/2007	1
ScanID	Location	Problem	Installed	Reference
Camera				
28593808	3rd Southeast Lobby Area	Damaged/Worn	04/19/2017	NFPA731 10.2.1
Electric Strike				
01001849	4th Stairwell A	Failed Operation	05/02/2008	NFPA731 10.2.1
Gate Operator				
01001825	1st Parking Lot Entrance	Damaged/Worn	04/01/2003	NFPA731 6.1.3
Intercom				
01001812	1st Loading Dock	Failed Test	01/02/2004	NFPA731 10.2.1
Radio				
01001810	1st Security Office	Failed Operation	09/01/2006	NFPA731 10.2.1
Turnstile				
01001823	1st Lobby Entrance	Damaged/Worn	09/01/2005	NFPA731 10.2.1
Code References				
NFPA731 10.2.1	System defects and malfunctions shall be corrected.			
NFPA731 6.1.3	The system shall be designed to control the unauthorized access of people, vehicles, and/or property through a portal as prescribed by the AHJ.			

Proposed Solutions Report

Generated by: BuildingReports.com

Building: 2018 Sample Inspection Report

The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.

ScanID	Location	Solution	Model #	Cost	Fix
Camera					
28593808	3rd Southeast Lobby Area	Replace	MPX851Z	T/M	<input type="checkbox"/>
Electric Strike					
01001849	4th Stairwell A	Replace	8G435	\$87.00	<input type="checkbox"/>
Gate Operator					
01001825	1st Parking Lot Entrance	Replace	G-326	T/M	<input type="checkbox"/>
Intercom					
01001812	1st Loading Dock	Replace	BR442	T/M	<input type="checkbox"/>
Radio					
01001810	1st Security Office	Replace	Z5000	\$375.00	<input type="checkbox"/>
Turnstile					
01001823	1st Lobby Entrance	Replace	K-4778	T/M	<input type="checkbox"/>

Inspection & Testing

Generated by: BuildingReports.com

Building: 2018 Sample Inspection Report

The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.

Device Type	Location	Service	Time	Date
Passed				
Access				
Access Sensor	1st Loading Dock Entrance	Tested	6:23:09 AM	01/02/2018
Access Sensor	4th Suite 400	Tested	6:08:18 AM	01/02/2018
Access Sensor	5th Suite 500	Tested	6:06:12 AM	01/02/2018
Electric Lock	2nd West Hallway Outside of Med Room 2-9	Tested	5:26:02 PM	01/02/2018
Electric Strike	1st Security Office	Tested	7:14:25 AM	01/02/2018
Electric Strike	5th Stairwell A	Tested	6:58:18 AM	01/02/2018
Electric Strike	5th Stairwell B	Tested	7:19:27 AM	01/02/2018
Magnetic Lock	1st Maintenance Shop	Tested	7:34:02 AM	01/02/2018
Reader	1st Loading Dock Entrance	Tested	6:26:23 AM	01/02/2018
Reader	4th Suite 400	Tested	6:43:14 AM	01/02/2018
Reader	5th Suite 500	Tested	6:48:10 AM	01/02/2018
Request to Exit	1st Northeast Emergency Exit	Tested	7:38:16 AM	01/02/2018
Alarm				
Biometric Device	3rd Computer Room	Tested	7:51:33 AM	01/02/2018
Button	3rd Computer Room	Tested	7:58:55 AM	01/02/2018
Button	5th Suite 520	Tested	8:05:20 AM	01/02/2018
Door Contact	5th Suite 520	Tested	8:07:06 AM	01/02/2018
Motion Sensor	5th Suite 520	Tested	8:08:22 AM	01/02/2018
Motion Sensor	5th Suite 520	Tested	8:09:28 AM	01/02/2018
Control				
Annunciator	1st Security Office	Tested	8:35:42 AM	01/02/2018
Batteries	1st Security Office-Communicator	Tested	8:37:15 AM	01/02/2018
Communicator	1st Security Office	Tested	8:39:32 AM	01/02/2018
Control Panel	1st Security Office	Tested	8:45:50 AM	01/02/2018
Power Supply	1st Security Office	Tested	8:47:49 AM	01/02/2018
Power Supply	1st Electrical Room	Tested	2:55:30 PM	01/02/2018
Printer	1st Security Office	Tested	8:51:12 AM	01/02/2018
Nurse Call				
Bath Station	5th Room 541	Tested	2:20:49 PM	01/02/2018
Code Blue	5th Nurse Station	Tested	2:23:53 PM	01/02/2018
Emergency Call	5th Nurse's Desk	Tested	2:37:37 PM	01/02/2018
IV Pump	5th Nurse's Desk	Tested	2:35:39 PM	01/02/2018
Nurse Console	5th Nurse Station	Tested	2:26:03 PM	01/02/2018

Device Type	Location	Service	Time	Date
Patient Monitor	5th Nurse's Desk	Tested	2:28:20 PM	01/02/2018
Perimeter				
Barrier	1st Main Entrance	Tested	9:13:16 AM	01/02/2018
Fence	1st Surrounding Generator Area	Inspected	9:16:43 AM	01/02/2018
Turnstile	1st Lobby Entrance	Tested	9:59:55 AM	01/02/2018
Turnstile	1st Lobby Entrance	Tested	10:00:25 AM	01/02/2018
Vehicle	1st Loading Dock Reserved Space	Inspected	9:47:32 AM	01/02/2018
Personnel				
Air Monitor	5th Mechanical Room	Tested	10:15:17 AM	01/02/2018
Breathing Apparatus	1st Security Office	Inspected	10:35:58 AM	01/02/2018
Defibrillator	1st Security Office	Tested	10:36:05 AM	01/02/2018
Fall Protection	Roof North Corner	Tested	11:26:09 AM	01/02/2018
First Aid	1st Security Office	Tested	10:46:15 AM	01/02/2018
Radio	1st Security Office	Tested	11:10:59 AM	01/02/2018
Weapon	1st Security Office	Tested	11:14:56 AM	01/02/2018
Video				
Camera	3rd East Entrance Area Between motion sensor doors	Tested	5:20:19 PM	01/02/2018
PTZ Unit	1st Security Office	Tested	1:22:43 PM	01/02/2018
<i>Failed/Other</i>				
Access				
Electric Strike	4th Stairwell A	Tested	8:53:23 AM	01/02/2018
Perimeter				
Gate Operator	1st Parking Lot Entrance	Inspected	9:40:49 AM	01/02/2018
Turnstile	1st Lobby Entrance	Inspected	9:58:28 AM	01/02/2018
Personnel				
Intercom	1st Loading Dock	Tested	10:58:26 AM	01/02/2018
Radio	1st Security Office	Tested	11:10:27 AM	01/02/2018
Video				
Camera	3rd Southeast Lobby Area	Tested	3:01:10 PM	01/02/2018
<i>Untested</i>				
Perimeter				
Barrier	1st Main Entrance			
Barrier	Ground Parking Lot Entrance			
Turnstile	1st Lobby Entrance			

Video Systems Testing

Generated by: BuildingReports.com

Building: 2018 Sample Inspection Report						
<i>Passed</i>						
Camera						
Location		Type	Description	Coverage	ScanID	
3rd East Entrance Area Between motion sensor doors		POE	Network	Day/Night	28593834	
Format	Size	Manufacturer	Lens Size	Lens Type	Voltage	Mount
Coaxial	2"	FLIR	Auto-Iris	25mm	12 VAC	Recessed
MAC Address		IP Address			VLAN ID	
AC8112147029						
PTZ Unit						
Voltage	Size	Type	Description	Mount	ScanID	
120 VAC	3"	Pan & Tilt	Variable Speed	Wall	01001799	
MAC Address		IP Address			VLAN ID	
<i>Failed/Other</i>						
Camera						
Location		Type	Description	Coverage	ScanID	
3rd Southeast Lobby Area		POE	Network	Day/Night	28593808	
Format	Size	Manufacturer	Lens Size	Lens Type	Voltage	Mount
IP	2"	FLIR	Auto-Iris	25mm	12 VAC	Recessed
MAC Address		IP Address			VLAN ID	
AC8112147029		10.0.1.1.				

Access Control Testing

Generated by: *BuildingReports.com*

Building: 2018 Sample Inspection Report						
<i>Passed</i>						
Access Sensor						
Location	Type	Mount	Voltage	Coverage	ScanID	
1st Loading Dock Entrance	Pressure Mat				01001857	
MAC Address	IP Address			VLAN ID		
Location	Type	Mount	Voltage	Coverage	ScanID	
4th Suite 400	PIR				01001860	
MAC Address	IP Address			VLAN ID		
Location	Type	Mount	Voltage	Coverage	ScanID	
5th Suite 500	PIR				01001861	
MAC Address	IP Address			VLAN ID		
Electric Lock						
Location	Type	Mount	Voltage	Description	ScanID	
2nd West Hallway Outside of Med Room 2-9	Actuator Controlled	Recessed	12 VDC	Wireless Lock	28593833	
MAC Address	IP Address			VLAN ID		
BJD00493194						
Electric Strike						
Location	Type	Mount	Voltage	Description	ScanID	
1st Security Office	Heavy Duty				01001846	
MAC Address	IP Address			VLAN ID		
Location	Type	Mount	Voltage	Description	ScanID	
5th Stairwell A	Heavy Duty				01001850	
MAC Address	IP Address			VLAN ID		
Location	Type	Mount	Voltage	Description	ScanID	
5th Stairwell B	Heavy Duty				01001845	
MAC Address	IP Address			VLAN ID		
Magnetic Lock						
Location	Type	Mount	Voltage	Description	ScanID	
1st Maintenance Shop	Surface				01001841	
MAC Address	IP Address			VLAN ID		

Reader						
Location	Type	Mount	Voltage	Description	ScanID	
1st Loading Dock Entrance	Mag Stripe				01001856	
MAC Address	IP Address			VLAN ID		
Location	Type	Mount	Voltage	Description	ScanID	
4th Suite 400	Mag Stripe				01001853	
MAC Address	IP Address			VLAN ID		
Location	Type	Mount	Voltage	Description	ScanID	
5th Suite 500	Mag Stripe				01001852	
MAC Address	IP Address			VLAN ID		
Request to Exit						
Location	Type	Description	Timing	ScanID		
1st Northeast Emergency Exit	Delayed Egress		5	01001840		
MAC Address	IP Address			VLAN ID		
<i>Failed/Other</i>						
Electric Strike						
Location	Type	Mount	Voltage	Description	ScanID	
4th Stairwell A	Heavy Duty				01001849	
MAC Address	IP Address			VLAN ID		

Alarm & Intrusion Detection Testing

Generated by: *BuildingReports.com*

Building: 2018 Sample Inspection Report					
<i>Passed</i>					
Biometric Device					
Location	Type	Mount	Voltage	Zone/Address	ScanID
3rd Computer Room	Iris Scanning	Flush	120 VAC	1-04	01001839
Button					
Location	Type	Mount	Size	Zone/Address	ScanID
3rd Computer Room	Iris Scanning	Wall	1/3"	1-05	01001838
Location	Type	Mount	Size	Zone/Address	ScanID
5th Suite 520	Emergency	Flush	1/4"	1-05	01001837
Door Contact					
Location	Type	Mount	Size	Zone/Address	ScanID
5th Suite 520	Magnetic	Ceiling	1"	1-06	01001836
Motion Sensor					
Location	Type	Mount	Voltage	Zone/Address	ScanID
5th Suite 520	Photoelectric Beam	Ceiling	120 VAC	1-07	01001835
Location	Type	Mount	Voltage	Zone/Address	ScanID
5th Suite 520	Photoelectric Beam	Ceiling	120 VAC	1-08	01001834

Personnel Safety Testing

Generated by: *BuildingReports.com*

Building: 2018 Sample Inspection Report				
<i>Passed</i>				
Air Monitor				
Location	Type	Manufacturer	ScanID	
5th Mechanical Room	Indoor Air Quality	Andover	01001820	
Breathing Apparatus				
Location	Type	Size	Manufacturer	ScanID
1st Security Office	Self-contained		Elite	01001815
Defibrillator				
Location	Type	Calibration	Manufacturer	ScanID
1st Security Office	Portable	03/05/2008	Advanced Technology	01001814
Fall Protection				
Location	Type	Manufacturer	ScanID	
Roof North Corner	Roof Anchor	Tamron	01001805	
First Aid				
Location	Type	Manufacturer	ScanID	
1st Security Office	5-shelf Station	Johnson & Johnson	01001813	
Radio				
Location	Type	Manufacturer	ScanID	
1st Security Office	Two-Way	Motorola	01001808	
Weapon				
Location	Type	Description	ScanID	
1st Security Office	Pepper Spray	Trigger Bottle	01001806	
<i>Failed/Other</i>				
Intercom				
Location	Type	Manufacturer	ScanID	
1st Loading Dock	Wireless	Multitone Wireless	01001812	
Radio				
Location	Type	Manufacturer	ScanID	
1st Security Office	Two-Way	Motorola	01001810	

Perimeter Security Testing

Generated by: *BuildingReports.com*

Building: 2018 Sample Inspection Report						
<i>Passed</i>						
Barrier						
Location	Type		Description		ScanID	
1st Main Entrance	Barricades		Steel Plated		01001827	
Fence						
Location	Type	Size	Coverage	ScanID		
1st Surrounding Generator Area	Chain Link	6'	25' x 40'	01001826		
Turnstile						
Location	Type		Description		ScanID	
1st Lobby Entrance	Rotating Gate				01001822	
Location	Type		Description		ScanID	
1st Lobby Entrance	Rotating Gate				01001821	
Vehicle						
Manufacturer	Model	Type	Description		ScanID	
Ford	F-150	Truck			01001824	
<i>Failed/Other</i>						
Gate Operator						
Location	Type	Description	Size	Coverage	ScanID	
1st Parking Lot Entrance	Barrier Arm	Standard	1/2hp	Fail Safe	01001825	
Turnstile						
Location	Type		Description		ScanID	
1st Lobby Entrance	Wheelchair Access				01001823	
<i>Untested</i>						
Barrier						
Location	Type		Description		ScanID	
1st Main Entrance	Planter		40 Gal Box Planter		01821128	
Location	Type		Description		ScanID	
Ground Parking Lot Entrance	Planter		40 Gal Box Planter		01821125	
Turnstile						
Location	Type		Description		ScanID	
1st Lobby Entrance	Drop Arm				01821180	

Nurse Call System Testing

Generated by: BuildingReports.com

Building: 2018 Sample Inspection Report			
<i>Passed</i>			
Bath Station			
Location	Type	Description	ScanID
5th Room 541	Emergency	Push-Button	01001796
Code Blue			
Location	Type	Description	ScanID
5th Nurse Station	Dual-Action	Toggle	01001795
Emergency Call			
Location	Type	Description	ScanID
5th Nurse's Desk	Epilepsy	Dual-Action Toggle	01001791
IV Pump			
Location	Type	Description	ScanID
5th Nurse's Desk	LCD	Portable	01001792
Nurse Console			
Location	Type	Description	ScanID
5th Nurse Station	LCD	Desktop	01001794
Patient Monitor			
Location	Type	Description	ScanID
5th Nurse's Desk	Wrist	Wireless	01001793

Control Equipment Testing

Generated by: *BuildingReports.com*

Building: 2018 Sample Inspection Report							
<i>Passed</i>							
Annunciator							
Type	Location	Description	Mount	Serial Number	ScanID		
PC Based	1st Security Office			83257	01001833		
Batteries							
Type	Location	Comment	Size	Amps	Volts	Pre Test	Post Test
Sealed Lead Acid	1st Security Office-Communicator	Passed		7.5	12 VDC	13.7	13.4
Control Panel							
Type	Location	Description	Mount	Amps	Volts	ScanID	
Access Control	1st Security Office		Flush	8	24 VAC	01001830	
Software Version	Software Date						
3.0	03/05/2008						
Power Supply							
Type	Location	Description	Mount	Amps	Volts	ScanID	
Fail Safe	1st Security Office	Door Power	Surface	8	24 VAC	01001829	
Type	Location	Description	Mount	Amps	Volts	ScanID	
Fail Safe	1st Electrical Room		Surface	8	24 VAC	01001790	
Printer							
Type	Location	Description	Voltage	Serial Number	ScanID		
Laser	1st Security Office	ID Card		63233	01001828		

Inventory & Warranty Report

Generated by: BuildingReports.com

Building: 2018 Sample Inspection Report

The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.

Device or Item	Category	% of Inventory	Quantity
Barrier	Perimeter	5.56%	3
Turnstile	Perimeter	7.41%	4
Access Sensor	Access	5.56%	3
Reader	Access	5.56%	3
Electric Strike	Access	7.41%	4
Magnetic Lock	Access	1.85%	1
Request to Exit	Access	1.85%	1
Biometric Device	Alarm	1.85%	1
Button	Alarm	3.70%	2
Door Contact	Alarm	1.85%	1
Motion Sensor	Alarm	3.70%	2
Annunciator	Control	1.85%	1
Batteries	Control	1.85%	1
Communicator	Control	1.85%	1
Control Panel	Control	1.85%	1
Power Supply	Control	3.70%	2
Printer	Control	1.85%	1
Fence	Perimeter	1.85%	1
Gate Operator	Perimeter	1.85%	1
Vehicle	Perimeter	1.85%	1
Air Monitor	Personnel	1.85%	1
Breathing Apparatus	Personnel	1.85%	1
Defibrillator	Personnel	1.85%	1
First Aid	Personnel	1.85%	1
Intercom	Personnel	1.85%	1
Radio	Personnel	3.70%	2
Weapon	Personnel	1.85%	1
Fall Protection	Personnel	1.85%	1
PTZ Unit	Video	1.85%	1
Bath Station	Nurse Call	1.85%	1
Code Blue	Nurse Call	1.85%	1
Nurse Console	Nurse Call	1.85%	1
Patient Monitor	Nurse Call	1.85%	1
IV Pump	Nurse Call	1.85%	1
Emergency Call	Nurse Call	1.85%	1
Camera	Video	3.70%	2

Device or Item	Category	% of Inventory	Quantity	
Electric Lock	Access	1.85%	1	
Type	Qty	Model #	Description	Install Date
<i>In Service - 90 Days - 1 Year</i>				
FLIR				
Camera	2	MPX851Z	POE	04/19/2017
Electric Lock	1	MPX851Z	Actuator Controlled	04/19/2017
<i>In Service - 5 Years to 10 Years</i>				
HID				
Reader	3	Thinline II	Mag Stripe	01/04/2010
Advanced Technology				
Defibrillator	1	DF-445	Portable	01/01/2009
Elite				
Breathing Apparatus	1	BA-667	Self-contained	01/01/2009
Sentry				
Electric Strike	4	8G435	Heavy Duty	05/02/2008
<i>In Service - 10 Years to 15 Years</i>				
DSC				
Access Sensor	2	011345	PIR	02/06/2008
Identix				
Button	1	08090	Emergency	10/05/2007
Button	1	08090	Iris Scanning	10/05/2007
SDC				
Door Contact	1	S448	Magnetic	10/05/2007
Tripp-Lite				
Motion Sensor	2	TR278	Photoelectric Beam	10/05/2007
DSC				
Access Sensor	1	011346	Pressure Mat	09/06/2007
Notifier				
Power Supply	1	FCPS-24S8	Fail Safe	08/01/2007
Philips				
PTZ Unit	1	MP-328	Pan & Tilt	08/01/2007
Johnson & Johnson				
First Aid	1	10464	5-shelf Station	04/02/2007
Motorola				
Radio	2	Z5000	Two-Way	09/01/2006
ProCon				
Weapon	1	Silv005	Pepper Spray	09/01/2006
Tamron				
Fall Protection	1	TA-680	Roof Anchor	09/01/2006
Detex				
Request to Exit	1	DX276	Delayed Egress	03/08/2006

Type	Qty	Model #	Description	Install Date
Identix				
Biometric Device	1	08090	Iris Scanning	03/08/2006
Lenel				
Magnetic Lock	1	LN234	Surface	03/08/2006
ups				
Barrier	1	BoxPlan	Planter	10/05/2005
USP				
Barrier	1	BoxPlan	Planter	10/05/2005
Kantech				
Turnstile	2	K-4778	Rotating Gate	09/01/2005
Turnstile	1	K-4778	Wheelchair Access	09/01/2005
Aiphone				
Bath Station	1	A-697	Emergency	04/01/2005
Code Blue	1	A-694	Dual-Action	04/01/2005
Emergency Call	1	A-650	Epilepsy	04/01/2005
IV Pump	1	A-680	LCD	04/01/2005
Patient Monitor	1	A-690	Wrist	04/01/2005
Toshiba				
Nurse Console	1	T-360	LCD	04/01/2005
Bosch				
Control Panel	1	B4101	Access Control	09/21/2004
DSC				
Annunciator	1	DS-276	PC Based	09/21/2004
Panasonic				
Printer	1	38EX	Laser	09/21/2004
Radionics				
Communicator	1	5406	Digital Communicator	09/21/2004
Werker				
Batteries	1	12-7.5F	Sealed Lead Acid	09/21/2004
Cooper Wheelock				
Power Supply	1	PS-12/24-8MP	Fail Safe	09/20/2004
Multitone Wireless				
Intercom	1	BR442	Wireless	01/02/2004
Accessure				
Turnstile	1	TS777	Drop Arm	10/16/2003
Ford				
Vehicle	1	F-150	Truck	04/01/2003
Gate Guard				
Gate Operator	1	G-326	Barrier Arm	04/01/2003
<i>In Service - 15 Years to 25 Years</i>				
Andover				
Air Monitor	1	ASQN3	Indoor Air Quality	02/01/2000

Type	Qty	Model #	Description	Install Date
Checkpoint				
Barrier	1	CK-587	Barricades	04/06/1995
<i>In Service - 25 Years or Older</i>				
Checkpoint				
Fence	1	CK-587	Chain Link	03/01/1984

Zone Address Report

Generated by: BuildingReports.com

Building: 2018 Sample Inspection Report				
<p><i>The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.</i></p>				
Address	Device Type	Location	Type	ScanID
Zone/Circuit: 04				
	Biometric Device	3rd Computer Room	Iris Scanning	01001839
Zone/Circuit: 05				
	Button	3rd Computer Room	Iris Scanning	01001838
	Button	5th Suite 520	Emergency	01001837
Zone/Circuit: 06				
	Door Contact	5th Suite 520	Magnetic	01001836
Zone/Circuit: 07				
	Motion Sensor	5th Suite 520	Photoelectric Beam	01001835
Zone/Circuit: 08				
	Annunciator	1st Security Office	PC Based	01001833
	Batteries	1st Security Office-Communicator	Sealed Lead Acid	01001832
	Communicator	1st Security Office	Digital Communicator	01001831
	Motion Sensor	5th Suite 520	Photoelectric Beam	01001834